



**All Wheel Drive Auto**

8410 120th Ave NE  
Kirkland, WA 98033-8024  
(425) 828-3600

**INSPECTION**

**# 34309**

Printed: 10:13:27 AM 12/23/20

AWD AUTO SALES  
AUTO MART MONROE  
224 WEST MAIN  
Monroe WA 98272

- 0 item(s) require immediate service.
- 0 item(s) will require service soon.
- 68 item(s) are in good condition.

MAKE & MODEL	LICENSE	VIN	ENGINE SIZE	MILEAGE	COLOR
2006 SUBARU IMPREZA WRX WRX	AMS0623	JF1GD79636G521724	2.5L H4 FI DOHC	122877 /	BLACK

**Lights**

- Headlights
- Fog
- Brake Lights
- Signal Flasher
- Backup Lights
- License
- Interior
- Check Engine Light
- Tire Pressure Light
- ABS Light
- Air Bag Light
- AT Temp Light
- Misc Light

REPLACED

**Miscellaneous**

- Belts
- Horn
- Air Conditioning Vent Temp
- Door Locks
- Window Functions
- Mirror Functions
- Clutch Master Cylinder
- Differentials
- Battery System Test
- Exhaust
- Windshield Wipers

REPLACED

REPLACED

**Suspension/Steering**

- Tie Rod Ends

MAKE & MODEL	LICENSE	VIN	ENGINE SIZE	MILEAGE	COLOR
2006 SUBARU IMPREZA WRX WRX	AMS0623	JF1GD79636G521724	2.5L H4 FI DOHC	122877 /	BLACK

### Suspension/Steering

- ✓ Axle
- ✓ Ball Joints
- ✓ Rack And Pinion
- ✓ Struts
- ✓ CV Boots
- ✓ Rack And Pinion Boots
- ✓ Wheel Bearings
- ✓ Alignment
- ✓ Sway Bar end Links & Bushings
- ✓ Lower Control Arm Bushings

### Filters

- ✓ Air Filter
- ✓ Fuel Filter
- ✓ PCV
- ✓ Cabin Fliter

### Fluids


- ✓ Coolant REPLACED
- ✓ Brake Fluid REPLACED
- ✓ Transmission Fluid REPLACED
- ✓ Differential Fluid REPLACED
- ✓ Power Steering Fluid
- ✓ Washer Fluid
- ✓ Engine Oil Level / Oil Sticker REPLACED

### Engine Leaks

- ✓ Head Gaskets OIL\_\_\_ COOLANT\_\_\_ INTERNAL\_\_\_ MONITOR\_\_\_
- ✓ Oil Leaks@
- ✓ POWER STEERING PUMP LEAKS\_\_\_ OK\_\_\_

### Cooling

- ✓ Radiator
- ✓ Radiator Cap REPLACED
- ✓ Water Pump
- ✓ Hoses REPLACED RADIATOR HOSES
- ✓ Leaks
- ✓ Thermostat



MAKE & MODEL	LICENSE	VIN	ENGINE SIZE	MILEAGE	COLOR
2006 SUBARU IMPREZA WRX WRX	AMS0623	JF1GD79636G521724	2.5L H4 FI DOHC	122877 /	BLACK

**Brakes**

- ✓ Front Brake Pads REPLACED
- ✓ Front Rotors REPLACED
- ✓ Rear Brake Pads \_\_\_90\_\_\_% Remaining (vis.est) \_\_\_9\_\_\_mm Remaining
- ✓ Rear Drums/Rotors L/R@ R/R@ Discard@
- ✓ Brake Lines
- ✓ Emergency Brake
- ✓ Brake Master Cylinder

**Tires**

- ✓ Rotate Tires
- ✓ PSI
- ✓ Tread Remaining L/F@ 9/32 R/F@ 9/32
- ✓ Tread Remaining L/R@ 9/32 R/R@ 9/32

**Recommended Mileage Service**

- ✓ Regular Service Recommended At \_\_\_ K Miles

**Tech Notes**

- ✓ :

