

All Wheel Drive Auto

8410 120th Ave NE
Kirkland, WA 98033-8024
(425) 828-3600

INSPECTION

50549

AWD AUTO SALES
AUTO MART MONROE
224 WEST MAIN
Monroe WA 98272

Printed: 3:48:25 PM 6/9/2016

Torque:

Mechanic Copy

MAKE & MODEL	LICENSE	VIN	ENGINE SIZE	MILEAGE	COLOR
2005 SUBARU FORESTER 2.5X X		JF1SG63695H752639	2.5L H4 SFI SOHC 16V	131740 /	SILVER

Lights

Good OK Bad	Headlights	POLISHED
Good OK Bad	Fog	REPLACED BULBS
Good OK Bad	Brake Lights	
Good OK Bad	Signal Flasher	
Good OK Bad	Backup Lights	
Good OK Bad	License	
Good OK Bad	Interior	
Good OK Bad	Check Engine Light	
Good OK Bad	Tire Pressure Light	
Good OK Bad	ABS Light	
Good OK Bad	Air Bag light	
Good OK Bad	AT Temp Light	
Good OK Bad	Misc Light	

Miscellaneous

Good OK Bad	Belts	REPLACED
Good OK Bad	Horn	
Good OK Bad	Air Conditioning Vent Temp	
Good OK Bad	Door Locks	
Good OK Bad	Window Functions	
Good OK Bad	Battery System Test	
Good OK Bad	Mirror Functions	
Good OK Bad	Clutch Master Cylinder	
Good OK Bad	Differentials	
Good OK Bad	Exhaust	
Good OK Bad	Windshield Wipers	

Suspension/Steering

Good OK Bad	CV Boots	
-------------	----------	--

MAKE & MODEL	LICENSE	VIN	ENGINE SIZE	MILEAGE	COLOR
2005 SUBARU FORESTER 2.5X X		JF1SG63695H752639	2.5L H4 SFI SOHC 16V	131740 /	SILVER

Suspension/Steering

Good OK Bad	Tie Rod Ends	
Good OK Bad	Wheel Bearings	
Good OK Bad	Ball Joints	
Good OK Bad	Rack And Pinion	
Good OK Bad	Axle	
Good OK Bad	Struts	
Good OK Bad	Sway Bar Bushings & Links	
Good OK Bad	Lower Control Arm Bushings	
Good OK Bad	Alignment	

Filters

Good OK Bad	Cabin Filter	
Good OK Bad	Air Filter	
Good OK Bad	Fuel Filter	
Good OK Bad	PCV	

Fluids

Good OK Bad	Coolant	
Good OK Bad	Brake Fluid	REPLACED
Good OK Bad	Transmission Fluid	
Good OK Bad	Differential Fluid	REPLACED
Good OK Bad	Power Steering Fluid	REPLACED
Good OK Bad	Washer Fluid	
Good OK Bad	Engine Oil Level / Oil Sticker	REPLACED

Engine Leaks

Good OK Bad	Head Gaskets	REPLACED
Good OK Bad	Oil Leaks @	OIL COOLER O-RINGS REPLACED
Good OK Bad	Power Steering Pump	Leaks_____ OK_____

Cooling

Good OK Bad	Radiator	
Good OK Bad	Radiator Cap	
Good OK Bad	Water Pump	
Good OK Bad	Leaks	
Good OK Bad	Hoses	REPLACED
Good OK Bad	Thermostat	REPLACED

Brakes

Good OK Bad	Front Brake Pads	90% REMAINING
-------------	------------------	---------------

MAKE & MODEL	LICENSE	VIN	ENGINE SIZE	MILEAGE	COLOR
2005 SUBARU FORESTER 2.5X X		JF1SG63695H752639	2.5L H4 SFI SOHC 16V	131740 /	SILVER

Brakes

Good OK Bad Front Rotors	L/F@	R/F@	Discard@
Good OK Bad Rear Brake Pads	70% REMAINING		
Good OK Bad Rear Drums/Rotors	L/R@	R/R@	Discard@
Good OK Bad Brake Master Cylinder			
Good OK Bad Brake Lines			
Good OK Bad Emergency Brake			

Tires

Good OK Bad PSI				
Good OK Bad Rotate Tires				
Good OK Bad Tread Remaining	L/F@	7/32	R/F@	8/32
Good OK Bad Tread Remaining	L/R@	7/32	R/R@	7/32

Recommended Mileage Service

Good OK Bad Regular Service Recommended At	_____ K Miles
---	---------------