

# All Wheel Drive Auto

8410 120th Ave NE  
Kirkland, WA 98033-8024  
(425) 828-3600

**INSPECTION**

**# 57047**

AWD AUTO SALES  
AUTO MART MONROE  
224 WEST MAIN  
Monroe WA 98272



0 item(s) require immediate service.

Printed: 11:36:52 AM 4/22/201



0 item(s) will require service soon.



66 item(s) are in good condition.

MAKE & MODEL	LICENSE	VIN	ENGINE SIZE	MILEAGE	COLOR
2013 Scion Scion Fr-S	[V16887]	JF1ZNAA13D2707454	1.8L L4 FI DOHC 16V	45185 /	GREY

## Lights

- ✓ Headlights
- ✓ Fog
- ✓ Brake Lights
- ✓ Signal Flasher REPLACED
- ✓ Backup Lights
- ✓ License
- ✓ Interior REPLACED
- ✓ Check Engine Light
- ✓ Tire Pressure Light REPLACED SENSORS
- ✓ ABS Light
- ✓ Air Bag light
- ✓ AT Temp Light
- ✓ Misc Light REPLACED

## Miscellaneous

- ✓ Belts
- ✓ Horn
- ✓ Air Conditioning Vent Temp
- ✓ Door Locks
- ✓ Window Functions
- ✓ Battery System Test REPLACED
- ✓ Mirror Functions
- ✓ Clutch Master Cylinder
- ✓ Differentials
- ✓ Exhaust
- ✓ Windshield Wipers










## Suspension/Steering

- ✓ CV Boots

MAKE & MODEL	LICENSE	VIN	ENGINE SIZE	MILEAGE	COLOR
2013 Scion Scion Fr-S	[V16887]	JF1ZNAA13D2707454	1.8L L4 FI DOHC 16V	45185 /	GREY


### Suspension/Steering

---

-  Tie Rod Ends
-  Wheel Bearings
-  Ball Joints
-  Rack And Pinion
-  Axle
-  Struts
-  Sway Bar Bushings & Links
-  Lower Control Arm Bushings
-  Alignment








### Filters

---

-  Cabin Filter
-  Air Filter                      HAS K&N PANEL
-  Fuel Filter
-  PCV




### Fluids

---

-  Coolant
-  Brake Fluid                      REPLACED
-  Transmission Fluid
-  Differential Fluid
-  Power Steering Fluid
-  Washer Fluid
-  Engine Oil Level / Oil Sticker                      REPLACED

### Engine Leaks

---

-  Head Gaskets                      OIL \_\_\_ COOLANT \_\_\_ INTERNAL \_\_\_ MONITOR
-  Oil Leaks @
-  Power Steering Pump                      Leaks \_\_\_ OK \_\_\_

### Cooling

---

-  Radiator
-  Radiator Cap
-  Water Pump
-  Leaks
-  Hoses
-  Thermostat

### Brakes

---

-  Front Brake Pads                      \_\_\_70% (visual est.)\_\_\_ 7mm Remaining

MAKE & MODEL	LICENSE	VIN	ENGINE SIZE	MILEAGE	COLOR
2013 Scion Scion Fr-S	[V16887]	JF1ZNAA13D2707454	1.8L L4 FI DOHC 16V	45185 /	GREY

---

**Brakes**

- ✓ Front Rotors L/F@ R/F@ Discard@
- ✓ Rear Brake Pads \_\_60% (visual est.)\_\_6mm Remaining
- ✓ Rear Drums/Rotors L/R@ R/R@ Discard@
- ✓ Brake Master Cylinder
- ✓ Brake Lines
- ✓ Emergency Brake

---

**Tires**

- ✓ PSI
- ✓ Rotate Tires
- ✓ Tread Remaining L/F@ 9/32 R/F@ 9/32
- ✓ Tread Remaining L/R@ 8/32 R/R@ 8/32

---

**Recommended Mileage Service**

- ✓ Regular Service Recommended At \_\_\_\_ K Miles