

# All Wheel Drive Auto

8410 120th Ave NE  
Kirkland, WA 98033-8024  
(425) 828-3600

**INSPECTION**

**# 59485**

AWD AUTO SALES  
AUTO MART MONROE  
224 WEST MAIN  
Monroe WA 98272



0 item(s) require immediate service.

Printed: 8:46:14 AM 9/15/2017



0 item(s) will require service soon.



66 item(s) are in good condition.

MAKE & MODEL	LICENSE	VIN	ENGINE SIZE	MILEAGE	COLOR
2011 Subaru Impreza 2.5I 2.5i	AZC9292	JF1GE6A68BH520527	2.5L H4 F SOHC 16V	44847 / 44852	

## Lights

- ✓ Headlights
- ✓ Fog
- ✓ Brake Lights
- ✓ Signal Flasher
- ✓ Backup Lights
- ✓ License
- ✓ Interior
- ✓ Check Engine Light
- ✓ Tire Pressure Light
- ✓ ABS Light
- ✓ Air Bag light
- ✓ AT Temp Light
- ✓ Misc Light

## Miscellaneous

- ✓ Belts REPLACED
- ✓ Horn
- ✓ Air Conditioning Vent Temp
- ✓ Door Locks
- ✓ Window Functions
- ✓ Battery System Test
- ✓ Mirror Functions
- ✓ Clutch Master Cylinder
- ✓ Differentials
- ✓ Exhaust
- ✓ Windshield Wipers

## Suspension/Steering

- ✓ CV Boots

MAKE & MODEL	LICENSE	VIN	ENGINE SIZE	MILEAGE	COLOR
2011 Subaru Impreza 2.5I 2.5i	AZC9292	JF1GE6A68BH520527	2.5L H4 F SOHC 16V	44847 / 44852	

### Suspension/Steering

- ✓ Tie Rod Ends
- ✓ Wheel Bearings
- ✓ Ball Joints
- ✓ Rack And Pinion
- ✓ Axle
- ✓ Struts
- ✓ Sway Bar Bushings & Links
- ✓ Lower Control Arm Bushings LOWER CONTROL ARM BUSHING SEAPING 1/10 - RECOMMEND MONITOR
- ✓ Alignment

### Filters

- ✓ Cabin Filter REPLACED
- ✓ Air Filter
- ✓ Fuel Filter FUEL FILTER IS IN THE TANK
- ✓ PCV

### Fluids

- ✓ Coolant
- ✓ Brake Fluid
- ✓ Transmission Fluid REPLACED
- ✓ Differential Fluid
- ✓ Power Steering Fluid REPLACED
- ✓ Washer Fluid WASHER FLUID TOPPED OFF
- ✓ Engine Oil Level / Oil Sticker REPLACED

### Engine Leaks

- ✓ Head Gaskets OIL\_\_\_ COOLANT\_\_\_ INTERNAL\_\_\_ MONITOR
- ✓ Oil Leaks @ OIL PAN DRAIN PLUG SEAPING 1/10 - RECOMMEND MONITOR
- ✓ Power Steering Pump Leaks\_\_\_ OK\_\_\_

### Cooling

- ✓ Radiator
- ✓ Radiator Cap
- ✓ Water Pump
- ✓ Leaks
- ✓ Hoses
- ✓ Thermostat

### Brakes

- ✓ Front Brake Pads 70% (visual est.) 7 mm Remaining

MAKE & MODEL	LICENSE	VIN	ENGINE SIZE	MILEAGE	COLOR
2011 Subaru Impreza 2.5i 2.5i	AZC9292	JF1GE6A68BH520527	2.5L H4 F SOHC 16V	44847 / 44852	

---

**Brakes**

- ✓ Front Rotors L/F@ 23.29 R/F@ 23.38 Discard@ 22MM - FRONT ROTORS ARE WARPED - RECOMMEND REPLACE
- ✓ Rear Brake Pads 60% (visual est.) 6 mm Remaining
- ✓ Rear Drums/Rotors L/R@ 9.94 R/R@ 9.91 Discard@ 8.50
- ✓ Brake Master Cylinder
- ✓ Brake Lines
- ✓ Emergency Brake

---

**Tires**

- ✓ PSI TIRE PRESSURE SET TO 34PSI
- ✓ Rotate Tires
- ✓ Tread Remaining L/F@ 9 /32 R/F@ 9 /32
- ✓ Tread Remaining L/R@ 9 /32 R/R@ 9 /32

---

**Recommended Mileage Service**

- ✓ Regular Service Recommended At \_\_\_\_K Miles